Date:	10/6/2015				
take no respo	nsibility for problems discovered	after the ins	pection da	<ul> <li>The City of Milwaukee, the Redevelopme te, or for omissions through error or oversigiteral Block Grant or HOME programs.</li> </ul>	
Exterior	Condition Report				
Location Site	Required Work  Landscaping	n/a □	Yes ☑	Note/Comments Self Help	\$ Cost 500.00
	Steps/Handrails	n/a ☑	Yes □		\$
	Service walks	n/a □	Yes 🗹		\$ 1,500.00
	Fencing	n/a 🗵	Yes □		\$
	Parking	n/a ☑	Yes □		\$
	Retaining walls	n/a □	Yes ☑	Permit Required	\$ 700.00
	Other	n/a □	Yes □		\$
_	Other	n/a □	Yes □		\$
Garage	Singles: repair	n/a ☑	Yes □		\$
	Shingles: Roof over existing	n/a 🗹	Yes □		\$
	Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 2,200.00
	Gutters/downspouts	n/a ☑	Yes □		\$
	Flashing	n/a ☑	Yes □		\$
	Fascia	n/a 🔲	Yes ☑		\$ 400.00
	Siding	n/a 🗆	Yes ☑		\$ 500.00
	Doors	n/a □	Yes ☑		\$ 1,150.00
	Windows	n/a 🗹	Yes □		\$
	Slab	n/a ☑	Yes □		\$
	Paint	n/a ☑	Yes □		\$
	Address Numbers	n/a □	Yes ☑		\$ 40.00
Porches	Other	n/a 🗆	Yes ☑	Structual	\$ 1,000.00
	Roof	n/a ☑	Yes □		\$
	Deck-upper	n/a ☑	Yes 🗆		\$
	Decklower	n/a ☑	Yes 🗆		\$
	Steps/handrails	n/a ☑	Yes □		\$
	Ceiling	n/a ☑	Yes □		\$
	Guardrails	n/a ☑	Yes 🗆		\$ 
	Structural	n/a ☑	Yes □		\$ 
	Paint	n/a ☑	Yes 🗆		\$
	Other	n/a □	Yes 🗆		\$ 
					 ·

**4822 West Scranton Place** 

Other □

Scope of Work for Property Located at:

Property is: Single Family ☑ Duplex □

## House

Chimney	n/a □	Yes 🔽		\$ 500.00
Shingles: repair	n/a ☑	Yes □		\$ 
Shingles: Roof over existing	n/a ☑	Yes □		\$ 
Shingles:Tear off & re-roof	n/a □	Yes 🗸		\$ 11,000.00
Gutters/downspouts	n/a □	Yes ☑		\$ 1,008.00
Flashing	n/a ☑	Yes □		\$ 
Eaves	n/a □	Yes ☑	-	\$ 500.00
Siding	n/a <u></u> ✓	Yes □		\$ 
Storm Doors	n/a ☑	Yes □		\$ 
Prime ("main") Doors	n/a □	Yes ☑		\$ 1,050.00
Storm Windows	n/a ☑	Yes □		\$ 
Prime ("main") Windows	n/a □	Yes ☑		\$ 6,200.00
Paint	n/a □	Yes ☑		\$ 500.00
Foundation	n/a □	Yes ☑	_	\$ 10,000.00
Electrical	n/a ☑	Yes □		\$ 
Other	n/a □	Yes ☑	2 basement Glass block windows	\$ 900.00
Other	n/a □	Yes ☑	Tuckpoint lannon stone	\$ 1,500.00
Other	n/a □	Yes ☑	Insulation	\$ 5,000.00
Other	n/a □	Yes 🗹	wood structual	\$ 3,000.00

Exterior: Estimated Cost:\*

49,148.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

	Unit: Entire unit (single family) Upper unit of duplex Required Work			Lower unit of duplex   Other	
Heating	Repair/replace boiler	n/a ☑	Yes □		\$
	Repair radiation	n/a ☑	Yes □		\$ 
	Repair/replace furnace	n/a □	Yes ☑		\$ 3,080.00
	Repair ductwork	n/a □	Yes 🗹		\$ 2,000.00
	Replace thermostat	n/a □	Yes ☑		\$ 100.00
	Repair/replace grilles	n/a ☑	Yes □		\$ 
	Tune boiler/furn. insp ht exchang	€n/a ☑	Yes □		\$ 
Electrical	Repair/replace receptacles	n/a □	Yes ☑		\$ 2,000.00
	Repair/replace switches	n/a □	Yes ☑		\$ 2,000.00
	Repair/replace fixtures	n/a □	Yes ☑		\$ 2,000.00
	Rewire	n/a □	Yes ☑		\$ 2,000.00
	Install outlets and circuits	n/a ☑	Yes □		\$ 
	Install outlets and circuits	n/a ☑	Yes □		\$ 
	Install outlets and circuits	n/a ☑	Yes 🗆		\$ 
	Upgrade service	n/a □	Yes ☑		\$ 1,796.00
	Other	n/a □	Yes ☑	Permit Required	\$ 85.00
<b>.</b>	Other	n/a □	Yes □	=	\$ 
Plumbing	Repair/replace kitchen sink	n/a □	Yes □		\$ 
	Repair/replace kitchen sink fauce	en/a □	Yes □	_	\$ 
	Repair/replace tub	n/a □	Yes □		\$ 
	Repair/replace tub faucet	n/a □	Yes □		\$ 
	Repair/replace toilet	n/a □	Yes □	-	\$ 
	Repair/replace lavatory	n/a <u></u> □	Yes □	_	\$ 
	Repair/replace lavatory faucet	n/a □	Yes □		\$ 
	Repair/replace wash tub	n/a □	Yes ☑		\$ 745.00
	Repair/replace wash tub faucet	n/a □	Yes ☑		\$ 315.00
	Unclog piping:	n/a □	Yes □		\$ 
	Other	n/a □	Yes ☑	Two complete Baths up stairs and down	\$ 4,400.00
	Repair water piping	n/a □	Yes 🗹		\$ 3,500.00
	Repair/replace water heater	n/a □	Yes 🗹	_	\$ 1,300.00
	Other	n/a □	Yes 🗹	Permit Required	\$ 85.00
	Other	n/a □	Yes ☑	complete Kitchen	\$ 1,455.00

**Interior Condition Report** 

Windows							
	Replace broken glass	n/a	1	Yes			
	Repair or replace sash	n/a	<b>√</b>	Yes		\$	
Doors	Repair or replace doors	n/a		Yes	7	\$	1,900.00
	Repair or repl. locks/latches	n/a		Yes	7	Self Help \$	550.00
Walls/Ceiling	gs Repair or repl. @ defective	n/a		Yes	7	Complete removal and reinstallation of all walls, Ceili \$	10,000.00
Paint	Repair or repl. @ defective	n/a		Yes	7	\$	4,000.00
Fire Safety	la stall and also (00 also made and	/					
	Install smoke/CO alarm:bsmt.	n/a	<u> </u>	Yes	<b>√</b>	Self Help \$	60.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	4	Self Help \$	60.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	<b>V</b>	Self Help \$	60.00
Handrails	Repair/replace defective	n/a		Yes	7	Self Help \$	372.00
Stairs	Repair defective	n/a	7	Yes		\$	
Floors	Repair defective	n/a	П	Yes	7	\$	9,500.00
Other	- Nopul Golden	n/a				\$	
		n/a		Yes		\$	
		n/a		Yes		\$	
		n/a		Yes		\$	
						Interior: Estimated Cost: \$	53,363.00
						Total Exterior and Interior Cost:* \$	102,511.00

## Inspected by Eric Yanke Date: 10/06/2015

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 West Mill Road.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.